From: <u>Larryafd</u>

To: <u>Harrington, Dwayne</u>
Subject: Re: EPA update

Date: Sunday, July 10, 2016 2:31:45 PM

Ok

Sent from my iPhone

On Jul 10, 2016, at 2:25 PM, Harrington, Dwayne < Harrington. Dwayne@epa.gov > wrote:

Thanks Larry

I'll contact you tomorrow

Sent from my iPhone

On Jul 10, 2016, at 2:24 PM, Larryafd < charger 22@aol.com > wrote:

That will work. The Sooner the pumpdown the better.

Sent from my iPhone

On Jul 10, 2016, at 2:21 PM, Harrington, Dwayne < Harrington. Dwayne@epa.gov > wrote:

We've discussed that with the VFD. I'll talk with them tomorrow

Sent from my iPhone

On Jul 10, 2016, at 2:00 PM, Larryafd < charger22@aol.com> wrote:

I agree that everything is a band aid at this point. If that relief valve lifts, it will blowing off for a long time. The other option is to put an a unmanned monitor (blitz fire) in the street connected to a fire hydrant on the corner and set it to a fog pattern. In the event of a release, you just have to open the hydrant to knock down the vapors. Fd has a blitz fire that can be used. No risk to responders and reduce off site risk too.

Thoughts?

Larry

The only safe way is pump it out now

Sent from my iPhone

On Jul 10, 2016, at 12:21 PM, Harrington, Dwayne < Harrington. Dwayne@epa.gov > wrote:

What do you think?

Sent from my iPhone

Begin forwarded message:

Daniel Johnson < djohnson@gesoncall.com >

Cc: "Norrell, Neil"

<Norrell.Neil@epa.gov>

Subject: RE: EPA

update

Tarping of the condensers would limit the immediate exposure and migration of a release from the condensers, but this will not limit or mitigate the hazard of the ammonia itself. In some ways, I would think that

allowing a relief valve that is at a greater height would be a little more safe in terms of exposure as we would not be forcing the vapors to the ground level and allowing them to migrate from there. There really is no good option to this other than to have the system deactivated and drained, everything else at this point is merely a band-aid patch.

Peter

From: Harrington,

Dwayne

[mailto:Harrington.Dwayne@epa.gov]

Sent: Sunday, July 10, 2016 11:18 AM **To:** Peter Johnson

<pjohnson@gesoncall.com>;

Jay Robertson

<jrobertson@gesoncall.com>;

Daniel Johnson

<<u>djohnson@gesoncall.com</u>>

Cc: Norrell, Neil

<<u>Norrell.Neil@epa.gov</u>>

Subject: Fwd: EPA

update

Tarping the condenser area to contain vapors.

What do you think?

Sent from my iPhone

Begin forwarded message:

From:

charger22@aol.com

Date:

July

10,

2016 at

11:09:41

AM

EDT

To:

rpagnini@vinelandcity.org, rtonetta@vinelandcity.org, Harrington.Dwayne@epa.gov

Subject:

Re:

EPA

update

Chief

We

could

use

some

salvage

covers

or

Home

Depot

type

tarps

over the

top of

the

condensers

and tie

them at

the

bottom

and

contain

any

vapor

which

may be

released.

lt

would

be

contained

to a very small area and stop a major off site release I have done this before to contain a leak Larry Original Message-From: Pagnini Robert <rpagnini@vinelandcity.org> To: charger22 <<u>charger22@aol.com</u>>; Tonetta Richard <rtonetta@vinelandcity.org>; Harrington, Dwayne < Harrington. Dwayne@epa.gov > Sent: Sun, Jul 10, 2016 11:02 am Subject: RE: EPA update Received and noted. I see the issues with the

relief valves.

Would it

be

possible

to build

a hood

type

system

that

could

encapsulate

the

relief

valves

without

compromising

the

valves

or

piping.

Then

direct

the

encapsulating

hood

device

to

discharge

to the

scrubber

in the

event of

a relief

valve

failure?

This

would

have to

be

designed

to be

free

standing

with its

own

supports

as to

not put

any

weight

or strain

on the

relief

valves

or

piping.

Sent

from my Windows Phone

From:

charger22@aol.com<mailto:charger22@aol.com>

Sent: 7/10/2016 9:40 To:

Tonetta

Richard<mailto:rtonetta@vinelandcity.org>;

Pagnini

Robert<mailto:rpagnini@vinelandcity.org>

Subject: EPA update

Here is the EPA update from yesterday,, Larry Update for

7/9/16:

Two of the four relief discharges have been secured and routed

discharge to the

scrubber,

however,

two

to

pressure

relief

valves

were

not able

to be

secured.

The

state of

deterioration

of the

vapor

pressure

relief

valves

was

found to

be so

severe

that a secure

connection

is not

possible.

The two

direct-

discharge

liquified

ammonia

direct-

discharge

vents

were

successfully

attached

to the

scrubber.

After a

review

of the

refrigeration

system,

EPA's

refrigeration

contractor

determined

that the

two

vapor

relief

valves

could

not be

isolated

to be

replaced

with

new

valves

even

temporarily

because

the

overall

refrigeration

system

is so

deteriorated

as to be

inoperable,

and

even

under

the best

conditions

the

attempted

operation

would

nevertheless

result in

а

significant

release

(greater

than

100 lbs)

of

residual

ammonia

in the

condensers,

which

would

be an

unacceptable

risk to

the

technicians

performing

the

work,

not to

mention

the

surrounding

community.

In

addition,

even if

the

valves

could

be

safely

removed,

should

their

connecting

screw-

threads

to the

condensers

be

similarly

deteriorated,

which is

highly likely, they could not be replaced and that would essentially shut the system down permanently

permanently. The refrigeration contractor also stated that. due to the design and deteriorated state and resulting inoperability of the system, a failure of one of the relief valves would ultimately result in the release from the valve of the

valve of the entire contents of the ammonia in the system (currently roughly estimated at ten to twelve thousand pounds),

which could not be secured because of the state of the system, and the resulting release could possibly last up to two weeks (10,000-12,000 lbs ammonia at 119 psi through a 1/2 vent line).

The facility owner told EPA that our and our contractors' activities on site were starting to make him nervous.

The relocation of the seven residences adjacent to the facility has been extended through Tuesday,

and

possibly

(probably)

beyond,

pending

further

assessment

and

developments.

PAD is

preparing

an

updated

fact

sheet.

The

VFD

has

lifted

the

shelter

in place

standby

advisory

for

neighborhood,

however,

the

emergency

notifications

and

instructions

for the

public in

the

event of

а

release

remain

intact.

IMAAC

release

projections

will be

revised

for

current

worst-

case

conditions.

EPA

refrigeration

system

and

structural

engineering

contractors

will be

on site

on

Monday

711/16

to

assess

the

refrigeration

system

and the

building

to

determine

what

wiiat

actions,

including immediate

emergency

actions,

are

required

to at

least

stabilize

the

situation,

including

what

options

are

available

to

address

the non-

secured

pressure relief

valves

on the

condensers.

RST

continues

24-hr

air

monitoring.